


Safety Camera Personal Injury Collision Data

Safety Camera Location: Montrose Avenue o/s 86/88


Site Number: T09/T10 Fixed site	Camera coordinates 508481, 223161:
Date established: June 1997	Speed Limit: 30mph

Plan of site including search area




Collision and casualty information

Year	Collisions			Casualties		
	KSI collisions	Slight collisions	Total collisions	KSI casualties	Slight casualties	Total casualties
1990	0	0	0	0	0	0
1991	0	2	2	0	3	3
1992	0	2	2	0	2	2
1993	0	2	2	0	3	3
1994	0	4	4	0	6	6
1995	0	2	2	0	2	2
1996	1	1	2	1	2	3
1997	0	2	2	0	2	2
1998	0	2	2	0	2	2
1999	0	0	0	0	0	0
2000	0	0	0	0	0	0
2001	0	2	2	0	2	2
2002	0	1	1	0	2	2
2003	0	1	1	0	1	1
2004	0	1	1	0	1	1
2005	0	1	1	0	1	1
2006	0	0	0	0	0	0
2007	0	2	2	0	4	4
2008	0	3	3	0	3	3
2009	0	3	3	0	4	4
2010	0	1	1	0	1	1
2011	0	0	0	0	0	0
2012	0	2	2	0	5	5
2013	0	0	0	0	0	0
2014	1	1	1	1	1	1
2015	0	1	1	0	3	3
2016	0	0	0	0	0	0
2017	0	3	3	0	6	6



Montrose Avenue



Speed Survey Data

Location of survey Montrose Avenue outside No 86/88								
Direction: T 09 Eastbound					Direction: T 10 Westbound			
Year	Speed Data				Speed Data			
	Average (mph)	85 th %	% over speed limit	% 15mph or over speed limit	Average (mph)	85 th %	% over speed limit	% 15mph or over speed limit
1990								
1991								
1992								
1993								
1994								
1995								
1996								
1997								
1998								
1999								
2000								
2001		30						
2002								
2003								
2004								
2005								
2006								
2007	25	28	4	0	26	30	9	0
2008	25	28	4	0	25	28	4	0
2009	25	29	6	0	25	28	4	0
2010	24	28	4	0	25	28	5	0
2011	25	28	3	0	25	28	3	0
2012	24	28	4	0	25	28	5	0
2013	24	28	3	0	25	28	4	0
2014	24	28	3	0				
2015	24	27						