


Safety Camera Personal Injury Collision Data

Safety Camera Location: Hitchin Road Southwest bound Dual Carriageway


Site Number: T 01 Fixed site	Camera coordinates: 510730, 224299
Date established: September 1997 Camera housing January 1995	Speed Limit: 40mph


Plan of site including search area



Collision and casualty information

Year	Collisions			Casualties		
	KSI collisions	Slight collisions	Total collisions	KSI casualties	Slight casualties	Total casualties
1990	0	1	1	0	1	1
1991	0	1	1	0	2	2
1992	0	1	1	0	1	1
1993	0	1	1	0	1	1
1994	0	0	0	0	0	0
1995	0	0	0	0	0	0
1996	0	0	0	0	0	0
1997	1	0	1	1	1	2
1998	0	0	0	0	0	0
1999	0	2	2	0	5	5
2000	0	0	0	0	0	0
2001	0	0	0	0	0	0
2002	0	1	1	0	2	2
2003	0	0	0	0	0	0
2004	0	0	0	0	0	0
2005	0	0	0	0	0	0
2006	0	1	1	0	3	3
2007	0	0	0	0	0	0
2008	1	0	1	1	1	2
2009	0	1	1	0	1	1
2010	0	0	0	0	0	0
2011	0	1	1	0	1	1
2012	0	1	1	0	1	1
2013	0	0	0	0	0	0
2014	0	0	0	0	0	0
2015	0	0	0	0	0	0
2016	0	2	2	0	3	3
2017	0	3	3	0	5	5





Speed Survey Data

Location of survey: Hitchin Road				
Direction: T 01 South West				
Year	Speed Data			
	Average (mph)	85 th %	% over speed limit	% 15mph or over speed limit
1990				
1991				
1992				
1993				
1994				
1995	No Data before 2001			
1996				
1997				
1998				
1999				
2000				
2001	42	47	40	7
2002				
2003				
2004	34	39	8	2
2005				
2006				
2007	33	38	10	1
2008	34	37	2	0
2009				
2010	34	37	2	0
2011*	27	30	13	0
2012	34	37	2	0
2013				
2014				
2015				

*NB 2011 Data subject to temporary 30 mph speed limit