

Safety Camera Personal Injury Collision Data

Safety Camera Location: Dunstable Road near Beresford Road

Site Number: T68/T69 Fixed site	Camera coordinates: 507458, 222326
Date established: July 2002	Speed Limit: 30mph


Plan of site including search area




Collision and casualty information

Year	Collisions			Casualties		
	KSI collisions	Slight collisions	Total collisions	KSI casualties	Slight casualties	Total casualties
1990	0	5	5	0	8	8
1991	1	3	4	1	3	4
1992	0	2	2	0	3	3
1993	1	1	2	1	2	3
1994	0	3	3	0	4	4
1995	0	4	4	0	6	6
1996	0	2	2	0	2	2
1997	0	5	5	0	7	7
1998	3	3	6	3	7	10
1999	0	6	6	0	9	9
2000	1	1	2	1	1	2
2001	0	0	0	0	0	0
2002	0	1	1	0	1	1
2003	1	1	2	1	1	2
2004	2	1	3	2	1	3
2005	0	2	2	0	2	2
2006	0	1	1	0	1	1
2007	0	1	1	0	1	1
2008	0	2	2	0	3	3
2009	0	3	3	0	3	3
2010	0	3	3	0	3	3
2011	0	3	3	0	9	9
2012	1	0	1	1	1	2
2013	0	3	3	0	3	3
2014	0	2	2	0	2	2
2015	0	1	1	0	5	5
2016	0	1	1	0	1	1
2017	0	2	2	0	6	6

Dunstable Road nr Beresford Road



Dunstable Road nr Beresford Road



Speed Survey Data

Location of survey: Dunstable Road near Beresford Road				
Direction: T68/69 Bi directional				
Year	Speed Data			
	Average (mph)	85 th %	% over speed limit	% 15mph or over speed limit
1991				
1992				
1993				
1994				
1995	No data before 2001			
1996				
1997				
1998				
1999				
2000				
2001				
2002				
2003	22	28	3	0
2004	21	28	1	0
2005	23	28	3	0
2006	22	28	4	0
2007	19	27	1	0
2008	22	26	1	0
2009	21	25	1	0
2010	21	25	0	0
2011	21	25	1	0
2012				
2013	21	25	1	0
2014	20	24	1	0
2015	20	24		