


Safety Camera Personal Injury Collision Data


Safety Camera Location: Stuart Street near Wellington Street	
Site Number: T 15 Fixed site	Camera coordinates: 508772, 221279
Date established: December 1998	Speed Limit: 30mph

Plan of site including search area:




Collision and casualty information:

Year	Collisions			Casualties		
	KSI collisions	Slight collisions	Total collisions	KSI casualties	Slight casualties	Total casualties
1990	2	12	14	2	16	18
1991	1	7	8	1	9	10
1992	0	5	5	0	6	6
1993	3	8	11	3	9	12
1994	5	6	11	5	9	14
1995	4	9	13	4	10	14
1996	2	12	14	2	13	15
1997	2	8	10	2	10	12
1998	1	12	13	1	13	14
1999	1	7	8	1	7	8
2000	0	5	5	0	6	6
2001	1	8	9	1	10	11
2002	1	3	4	1	3	4
2003	1	7	8	1	8	9
2004	0	6	6	0	9	9
2005	1	3	4	1	3	4
2006	0	5	5	0	5	5
2007	1	3	4	1	6	7
2008	0	3	3	0	4	4
2009	0	7	7	0	9	9
2010	2	10	12	2	12	14
2011	0	4	4	0	7	7
2012	1	6	7	1	9	10
2013	3	4	7	3	6	9
2014	1	10	11	1	15	16
2015	0	3	3	0	3	3
2016	1	4	5	1	4	5
2017	1	14	15	1	18	19



Stuart Street



Speed Survey Data:

Location of survey Stuart Street near Wellington Street				
Direction: T15 Eastbound				
Year	Speed Data			
	Average (mph)	85 th %	% over speed limit	% 15mph or over speed limit
1990				
1991				
1992				
1993				
1994				
1995	No data before 2001			
1996				
1997				
1998				
1999				
2000				
2001		27		
2002				
2003				
2004				
2005	24	30	13	0
2006	17	26	2	0
2007				
2008				
2009				
2010				
2011				
2012				
2013				
2014				