


Safety Camera Personal Injury Collision Data


Safety Camera Location: Sundon Park Road outside Lealands School	
Site Number: T 13/14 Fixed site	Camera coordinates: 505230, 225418
Date established: March 1998	Speed Limit: 30mph


Plan of site including search area:



Collision and casualty information:

Year	Collisions			Casualties		
	KSI collisions	Slight collisions	Total collisions	KSI casualties	Slight casualties	Total casualties
1990	0	6	6	0	7	7
1991	0	2	2	0	2	2
1992	1	8	9	1	8	9
1993	3	5	8	4	10	14
1994	0	3	3	0	3	3
1995	0	4	4	0	5	5
1996	1	7	8	1	8	9
1997	2	1	3	2	2	4
1998	0	0	0	0	0	0
1999	0	3	3	0	5	5
2000	0	2	2	0	2	2
2001	0	1	1	0	1	1
2002	0	2	2	0	2	2
2003	0	3	3	0	3	3
2004	0	2	2	0	2	2
2005	0	4	4	0	6	6
2006	1	2	3	1	3	4
2007	0	5	5	0	6	6
2008	1	1	2	1	1	2
2009	0	4	4	0	7	7
2010	1	3	4	1	3	4
2011	0	3	3	0	4	4
2012	1	0	1	1	0	1
2013	0	6	6	0	8	8
2014	0	0	0	0	0	0
2015	0	3	3	0	3	3
2016	0	4	4	0	4	4
2017	1	7	8	4	7	11





Speed Survey Data:

Location of survey: Sundon Park Road outside Lealands School								
Direction:T 13 Eastbound					Direction:T 14 Westbound			
Year	Speed Data				Speed Data			
	Average (mph)	85 th %	% over speed limit	% 15mph or over speed limit	Average (mph)	85 th %	% over speed limit	% 15mph or over speed limit
1990								
1991								
1992								
1993								
1994								
1995								
1996								
1997								
1998								
1999								
2000								
2001		30						
2002								
2003	24	28	2	0				
2004	24	18	2	0				
2005	26	29	11	0				
2006	24	29	6	0				
2007	26	29	8	0	25	29	5	0
2008	25	28	4	0				
2009	25	28	5	0	26	28	6	0
2010								
2011	25	28	2	0	26	29	7	0
2012								
2013	25	28	3	0	26	29	9	1
2014	25	28	3	0	26	29	9	0
2015					26	29		