


Safety Camera Personal Injury Collision Data


Safety Camera Location: Toddington Rd near Montague Avenue	
Site Number: T26/T27 Fixed site	Camera coordinates: 505205, 224726
Date established: November 1999	Speed Limit: 30mph

Plan of site including search area:




Collision and casualty information:

Year	Collisions			Casualties		
	KSI collisions	Slight collisions	Total collisions	KSI casualties	Slight casualties	Total casualties
1990	4	6	10	5	8	13
1991	1	5	6	1	6	7
1992	1	6	7	1	7	8
1993	0	2	2	0	3	3
1994	0	7	7	0	13	13
1995	2	6	8	2	6	8
1996	1	4	5	1	7	8
1997	0	2	2	0	2	2
1998	1	4	5	1	4	5
1999	0	1	1	0	1	1
2000	0	2	2	0	2	2
2001	0	2	2	0	2	2
2002	1	0	1	1	0	1
2003	0	0	0	0	0	0
2004	0	1	1	0	1	1
2005	0	2	2	0	2	2
2006	0	1	1	0	1	1
2007	1	2	3	1	2	3
2008	0	3	3	0	4	4
2009	0	4	4	0	4	4
2010	0	2	2	0	2	2
2011	0	2	2	0	2	2
2012	1	1	2	1	1	2
2013	0	2	2	0	2	2
2014	1	0	1	1	3	4
2015	1	0	1	1	0	1
2016	0	1	1	0	1	1
2017	1	3	4	1	3	4



Toddington Road



Speed Survey Data:

Location of survey Fixed Camera site Toddington Road near Montague Avenue								
Direction: T 26 Eastbound					Direction: T 27 Westbound			
Year	Speed Data				Speed Data			
	Average (mph)	85 th %	% over speed limit	% 15mph or over speed limit	Average (mph)	85 th %	% over speed limit	% 15mph or over speed limit
1990								
1991								
1992								
1993								
1994								
1995	No data before 2001							
1996								
1997								
1998								
1999								
2000								
2001	24	28	27	1				
2002								
2003	23	28	2	0				
2004	23	28	1	0				
2005	25	29	11	0				
2006	22	28	0	0				
2007	25	28	3	0	24	28	3	0
2008	25	28	3	0	23	27	2	0
2009	24	28	3	0	25	28	3	0
2010								
2011					24	28	4	0
2012								
2013	24	27	2	0	24	28	3	0
2014	24	28	2	0	24	27	2	0
2015								