


Safety Camera Personal Injury Collision Data

Safety Camera Location: Crawley Green Road

Site Number: T11/T12 Fixed site	Camera coordinates: 510130, 221371
Date established: March 1998	Speed Limit: 30mph


Plan of site including search area



Collision and casualty information


Year	Collisions			Casualties		
	KSI collisions	Slight collisions	Total collisions	KSI casualties	Slight casualties	Total casualties
1990	0	6	6	0	7	7
1991	0	1	1	0	1	1
1992	0	2	2	0	2	2
1993	1	4	5	1	6	7
1994	0	3	3	0	3	3
1995	1	4	5	1	4	5
1996	1	8	9	2	9	11
1997	1	3	4	1	4	5
1998	2	2	4	3	3	6
1999	0	3	3	0	3	3
2000	0	2	2	0	2	2
2001	0	2	2	0	2	2
2002	0	2	2	0	2	2
2003	0	1	1	0	2	2
2004	0	2	2	0	2	2
2005	0	1	1	0	1	1
2006	0	2	2	0	2	2
2007	1	6	7	1	9	10
2008	1	1	2	1	3	4
2009	0	0	0	0	0	0
2010	0	0	0	0	0	0
2011	2	2	4	2	2	4
2012	0	0	0	0	0	0
2013	0	4	4	0	7	7
2014	0	3	3	0	4	4
2015	0	2	2	0	5	5
2016	0	2	2	0	2	2
2017	0	6	6	0	10	10

Crawley Green Road



Crawley Green Road

Number of casualties



Year

Speed Survey Data

Location of survey								
Direction: T 11 Westbound					Direction: T 12 Eastbound			
Year	Speed Data				Speed Data			
	Average (mph)	85 th %	% over speed limit	% 15mph or over speed limit	Average (mph)	85 th %	% over speed limit	% 15mph or over speed limit
1991								
1992								
1993								
1994								
1995					No data before 2001			
1996								
1997								
1998								
1999								
2000								
2001		29						
2002								
2003								
2004	24	29	3	0				
2005	26	30	15	0				
2006								
2007	21	28	1	0				
2008	24	27	2	0	24	28	4	0
2009	24	27	2	0	24	28	4	0
2010	24	27	2	0	25	28	4	0
2011	24	27	2	0	24	28	4	0
2012	24	27	2	0	25	28	4	0
2013	24	27	2	0				
2014	24	27	2	0	24	27	2	0
2015								