


Safety Camera Personal Injury Collision Data


Safety Camera Location: Montrose Avenue near Blenheim Crescent	
Site Number: T07/T08 Fixed site	Camera coordinates: 508172, 223156
Date established: June 1997	Speed Limit: 30mph


Plan of site including search area:



Collision and casualty information:

Year	Collisions			Casualties		
	KSI collisions	Slight collisions	Total collisions	KSI casualties	Slight casualties	Total casualties
1990	0	0	0	0	0	0
1991	0	2	2	0	3	3
1992	0	2	2	0	2	2
1993	0	2	2	0	3	3
1994	0	4	4	0	6	6
1995	0	2	2	0	2	2
1996	1	1	2	1	2	3
1997	0	2	2	0	2	2
1998	0	2	2	0	2	2
1999	0	0	0	0	0	0
2000	0	0	0	0	0	0
2001	0	2	2	0	2	2
2002	0	1	1	0	2	2
2003	0	1	1	0	1	1
2004	0	1	1	0	1	1
2005	0	1	1	0	1	1
2006	0	0	0	0	0	0
2007	0	2	2	0	4	4
2008	0	3	3	0	3	3
2009	0	3	3	0	4	4
2010	0	1	1	0	1	1
2011	0	0	0	0	0	0
2012	0	2	2	0	5	5
2013	0	0	0	0	0	0
2014	1	1	2	1	1	2
2015	0	1	1	0	3	3
2016	0	0	0	0	0	0
2017	0	3	3	0	6	6





Speed Survey Data:

Location of survey : Montrose Avenue near Blenheim Crescent								
Direction: T 07 Eastbound					Direction: T 08 Westbound			
Year	Speed Data				Speed Data			
	Average (mph)	85 th %	% over speed limit	% 15mph or over speed limit	Average (mph)	85 th %	% over speed limit	% 15mph or over speed limit
1990								
1991								
1992								
1993								
1994								
1995			No data before 2001					
1996								
1997								
1998								
1999								
2000								
2001		30						
2002								
2003								
2004								
2005								
2006								
2007	24	29	4	0	25	28	3	0
2008	24	28	3	0	24	28	4	0
2009	24	28	3	0	25	28	4	0
2010	23	28	5	0				
2011	23	28	2	0				
2012	23	28	5	0	24	28	3	0
2013	24	28	3	0	24	27	2	0
2014	23	27	2	0	24	28	3	0
2015	23	28			28	24		