

Safety camera personal injury collision data

Camera T21: Stuart Street outside law courts

Author: Passenger Transport Unit

Contact: ptu@luton.gov.uk

Version: 1.0 (published)

Last updated: November 2018


Contents

Camera details	2
Plan of site including search area.....	2
Collision and casualty information	3
Speed survey data	4

Camera details


- **Location:** Stuart Street outside Law Courts
- **Site number:** T21 westbound
- **Camera coordinates:** 508909, 221141
- **Date established:** September 1998
- **Speed limit:** 30mph


Plan of site including search area



Collision and casualty information

Year	Collisions			Casualties		
	KSI collisions	Slight collisions	Total collisions	KSI casualties	Slight casualties	Total casualties
1990	2	12	14	2	16	18
1991	1	7	8	1	9	10
1992	0	5	5	0	6	6
1993	3	8	11	3	9	12
1994	5	6	11	5	9	14
1995	4	9	13	4	10	14
1996	2	12	14	2	13	15
1997	2	8	10	2	10	12
1998	1	12	13	1	13	14
1999	1	7	8	1	7	8
2000	0	5	5	0	6	6
2001	1	8	9	1	10	11
2002	1	3	4	1	3	4
2003	1	7	8	1	8	9
2004	0	6	6	0	9	9
2005	1	3	4	1	3	4
2006	0	5	5	0	5	5
2007	1	3	4	1	6	7
2008	0	3	3	0	4	4
2009	0	7	7	0	9	9
2010	2	10	12	2	12	14
2011	0	4	4	0	7	7
2012	1	6	7	1	9	10
2013	3	4	7	3	6	9
2014	1	10	11	1	15	16
2015	0	3	3	0	3	3
2016	1	4	5	1	4	5
2017	1	14	15	1	18	19





Speed survey data

Location of survey : Stuart Street outside law courts				
Direction: T21 Westbound				
Year	Speed data			
	Average (mph)	85 th %	% over speed limit	% 15mph or over speed limit
No data before 2005				
2005	24	30	13	0
2006	17	26	2	0
2007	24	28	4	0
2008	23	27	3	0
2009	25	28	3	0
2010	22	26	2	0
2011	24	27	3	0
2012	26	29	9	0
2013	24	28	3	0